Oil Field Environmental Incident Summary

Responsible Party: Unknown (Vandalism/Suspected Arson) **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: BENDIXON 1-10H

Field Name: GREEN LAKE Well File #: 29820

Date Incident: 4/16/2015 Time Incident: 20:00 Facility ID Number:

County: WILLIAMS Twp: 159 Rng: 100 Sec: 10 Qtr: SE SW

Location Description: Incident occurred at the Bendixon 1-10H well site.

Submitted By: Timothy Ilse Received By:

Contact Person: Steven Kilde

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Alamo Fire Department extinguished the fire.

Wastes Disposal Location:

Agencies Involved: Local Law Enforcement Local Fire Department

Updates

Date: 4/17/2015 Status: Reviewed - Assigned to Other Agency Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to fire, remained on location according to the report. NDIC retains oversight.